



5H9 51A

No threaded bolt holes for pulse generator here.



No feed holes here.

5H9 51B



5H9 51C

